CNCBallScrewKit-PM-728VT-UP Fig 1



Ref	Description	Part	Ref	Description	Part	Ref	Description	Part
1A	Ball Screw Base, Y Axis	Z7500	13	Ball Bearing 7001	Z7512	905	Flat Washer 5-12mm	Z7524
2	Ball Screw, Y Axis	Z7501	14	Nut Housing, Z Axis	Z7513	906A	Cap Screw M8-1.25 X 35	Z7525
3	Ball Screw, X Axis	Z7502	15	Column Cover, X Axis	Z7514	907	Flat Washer 5/16"[M8]	Z7526
4	Nut Housing, X Axis	Z7503	16A	Base, X Axis, R	Z7515	908	Cap Screw M5-.8 X 25	Z7527
5	Base, X Axis, L	Z7504	17	Cover, X Axis, R	Z7516	909	Lock Washer 5/16"[M8]	Z7528
6	Lock Nut	Z7505	18	Cover, X Axis, L	Z7517	910	Btn Hd Cap Screw 5*10	Z7529
7	Coupling, X/Y Axis	Z7506	19	Cover, Y Axis	Z7518	911	Cap Screw M6-1 X 16	Z7530
8A	Motor Base ,Y Axis	Z7507	20	Ball Bearing 7201	Z7519	912A	Cap Screw M5-.8 X 20	Z7531
9	Nut Housing,Y Axis	Z7508	901	Cap Screw M6-1 X 20	Z7520	913	Cap Screw M6-1 X 25	Z7532
10	Coupling, Z Axis	Z7509	902	Lock Washer 1/4" [M6]	Z7521	914	Flat Washer 1/4"[M6]	Z7533
11	Motor Base ,Z Axis	Z7510	903	Cap Screw M5-0.8 X 30	Z7522	915A	Cap Screw M5-.8 X 75	Z7534
12	Ball Screw, Z Axis	Z7511	904	Lock Washer 3/16" [M5]	Z7523	916A	Lock Washer M5	Z7535

Copyright © 2021 Quality Machine Tools, LLC